

## Lift-Off Deep Cleaner

27F6, 35K3, 73H5, 94Y2 Series

### Leaking

- 1) Is the trigger being depressed?
- 2) Verify that the cap is on securely on the water/solution tank.



**Correct:** gasket in place.



**Incorrect:** gasket not in place.

- 3) If the unit is still leaking, please contact one of our Authorized Service Centers to have a quality technician inspect your unit.